



NORTHWEST MOUNTAIN REGION RUNWAY INCURSION ACTION TEAM EVALUATION

**Spokane International Airport
December 11, 2001**

Jim Greene

Regional Runway Safety Program
Manager

Northwest Mountain Region
Federal Aviation Administration



Sedan versus DC-10





Definition of Runway Incursion

Any occurrence at an airport involving:

- **an aircraft**
- **a vehicle**
- **a person**
- **or an object**

on the ground that creates a collision hazard or results in loss of separation with an aircraft taking off, intending to take off, landing, or intending to land.




Runway Incursion Types

Runway incursions result from three types of surface incidents:

- **Operational Errors (OE)**
- **Pilot Deviations (PD)**
- **Vehicle/Pedestrian Deviations (V/PD)**



Trends



***431 Runway
Incursions During
CY 2000***




RUNWAY INCURSIONS

**CY97 to DATE
(as of 10/31/01)**

YTD Comparisons





10/31/2000 -- 366

10/31/2001 -- 226






Trends - Incursions by type





Trends

Pilot Deviations by operations type



256 Pilot Deviations during 2000



Top Incursion Airports

CY 2000

| LOCATION | LOC ID | OPS | RI | RATE |
|--|--------|---------|----|------|
| North Las Vegas Arpt, NV | VGT | 229,703 | 16 | 6.97 |
| Montgomery Field/San Diego, CA | MYF | 260,235 | 9 | 3.46 |
| Fort Lauderdale Exec, FL | FXE | 263,359 | 9 | 3.42 |
| Merrill Field, Anchorage, AK | MRI | 201,148 | 8 | 3.98 |
| Long Beach Arpt, CA | LGB | 416,766 | 8 | 1.92 |
| Logan Arpt, Boston, MA | BOS | 512,985 | 8 | 1.56 |
| Los Angeles, CA | LAX | 786,421 | 8 | 1.02 |
| Jeffco Arpt, Denver, CO | BJC | 177,319 | 7 | 3.95 |
| Concord Arpt, CA | CCR | 212,112 | 7 | 3.30 |
| Orange Co/John Wayne Arpt, Santa Ana, CA | SNA | 405,473 | 7 | 1.73 |
| Santa Barbara, CA | SBA | 163,865 | 6 | 3.66 |
| Lambert Fld, St. Louis, MO | STL | 490,779 | 6 | 1.22 |
| Phoenix Sky Harbor Arpt, AZ | PHX | 632,360 | 6 | 0.95 |
| Troutdale Arpt, OR | TTD | 76,252 | 5 | 6.56 |
| Teterboro Arpt, NJ | TEB | 272,201 | 5 | 1.84 |



Top Incursion Airports

CY 2000

| LOCATION | LOC ID | OPS | RI | RATE |
|------------------------------------|--------|---------|----|------|
| San Jose Arpt, CA | SJC | 300,365 | 5 | 1.67 |
| Bridgeport, CT | BDR | 90,760 | 4 | 4.41 |
| Greater Rockford Arpt, IL | RFD | 94,571 | 4 | 4.23 |
| McGhee Tyson Airport Knoxville, TN | TYS | 152,330 | 4 | 2.63 |
| Providence, RI | PVD | 157,470 | 4 | 2.54 |
| Sarasota/Bradenton Arpt, FL | SRQ | 174,515 | 4 | 2.29 |
| Palwaukee Muni, Chicago, IL | PWK | 185,236 | 4 | 2.16 |
| Albuquerque, NM | ABQ | 233,632 | 4 | 1.71 |
| Midway Arpt, Chicago, IL | MDW | 303,192 | 4 | 1.32 |
| Salt Lake City, UT | SLC | 370,681 | 4 | 1.08 |
| San Francisco, CA | SFO | 437,186 | 4 | 0.92 |
| Newark, NJ | EWR | 461,457 | 4 | 0.87 |
| Cincinnati-Covington Arpt, OH | CVG | 486,590 | 4 | 0.82 |
| O'Hare, Chicago, IL | ORD | 914,131 | 4 | 0.44 |



Sweeper versus DC-9





RISK ASSESSMENT



Why We Assessed Data

- As a result of feedback from 2000 Summit, needed to place runway incursions into another context
- Need a better way to track incursions
- Need a better understanding of where incursions happen
- Need a way to analyze data to get at causal factors
- Need to describe clearer picture of runway incursion incidents – *Not every incursion is a Tenerife*



Definitions


- A** Separation decreases to a point where the margin of safety is so low that the participants barely avoid a collision.*
- B** Separation decreases to a point where a significant potential for a collision existed.
- C** Separation decreases, or the potential for separation to decrease exists, but ample time and distance exist to avoid a potential collision.
- D** Meets the definition of a runway incursion, with little or no risk of a collision.

* The data contained in category A includes all accidents that occurred as a result of runway incursions (1997-2000), one in LaGuardia, NY & one in Sarasota, FL.

Not all runway incursions are “created equal”

Case 1


This incident meets the definition of a runway incursion, but there is little or no chance of collision.



- ▶ The potential for a collision is low
- ▶ Most frequently reported incursion

Case 2


This is a severe situation where the margin of safety is so low that a collision is barely avoided.



- ▶ Potential for a collision is high
- ▶ Typifies the common perception of a runway incursion
- ▶ More severe but less frequent

Runway Incursion Severity


The two simple cases illustrate that a variety of dimensions can dramatically impact the severity of a runway incursion.








Top 10 Airports
Runway Incursion TYPE
1997 - 2000



Number of Reported Runway Incursions by Severity

Figure 4.


**Severity Distribution of
Reported Runway Incursions
1997-2000**



Total = 1359

- ▶ The distribution of runway incursion severity categories from 1997 to 2000 indicates that the majority (81%) of the incidents was comprised of Category C & D events.

**Number of Reported Runway
Incursion by Severity**




Note:

- The total numbers are: 292, 325, 321, 431
- Accidents are listed as A events (1 accident in 1997, 2 accidents in 2000)
- Does not include 10 events with insufficient data

- ▶ There were 110 more reported runway incursions in 2000 than in 1999. Category C & D events accounted for 106 out of these 110 events.



% of Total Runway Incursions






Primary Causes of Runway Incursions

- Breakdown in Pilot/Ground Vehicle/Controller Communications
- Lack of Airport Familiarity
- Loss of Situational Awareness




Snow Plow versus Wingtip





- Home
- What's New ▶
- The Cockpit ▶
- Tower ▶
- On The Ground ▶
- Technologies ▶
- Human Element ▶
- Regions ▶
- Statistics & Data ▶
- About Us ▶
- Links ▶
- Archives

Runway Safety Program



[Contact Webmaster](#) [Web Site Policy & Issues](#)

99724



- Home
- What's New
- The Cockpit
- Tower
- On The Ground
- Technologies
- Human Element
- Regions
- Statistics & Data
- About Us
- Links
- Archives

Runway Safety Program

what's new

FAA Runway Safety Report



The FAA has recently developed and published the National Blueprint for Runway Safety, which provides a structured plan to improve runway safety across the nation. The Blueprint outlines several initiatives aimed at increasing runway safety. As part of implementing the Blueprint, the FAA has analyzed the severity of runway incursions for the first time. This analysis of runway incursion severity trends at towered airports in the United States will help guide implementation of these safety-related initiatives. Download report...(link to report).



Driving on the Airport Operations Area


The video, "Driving on the Airport Operations Area," and the study guide are essential elements in improving communications and operations when driving on any airport operations area. While this training is geared toward tower-controlled airports, any person driving on airport premises can benefit from its content. The focus of these training materials is to enhance the safety of vehicle operations on the airfield.





National Blueprint for Runway Safety

The Runway Safety Program is pleased to present the National










Airport Signs & Markings Quiz

Start Here

Place the number(s) of each sign or marking matching the description in the description box.
(Each sign or marking may be used once, more than once, or not at all.)

- A. Indicates you are approaching a runway
- B. Shows places you should not taxi an aircraft
- C. Indicates you do, or may, need ATC approval to cross
- D. Tells you the runway or taxiway you are on
- E. Sign giving you directions to a runway, taxiway, or other airport destination
- F. Indicates you're about to enter an area that could cause interference with an ILS signal
- G. Helps you find your way off a runway
- H. Confirms you are cleared onto a runway (tower - controlled airport)
- I. Used to indicate you're about to cross a runway approach or departure path
- J. Tells you where you should hold short of a crossing taxiway





U.S. Department
of Transportation

**Federal Aviation
Administration**

Advisory Circular

**Subject: PART 91 PILOT AND
FLIGHTCREW PROCEDURES
DURING TAXI OPERATIONS AND
PART 135 SINGLE-PILOT
OPERATIONS**

Date:
6/18/01
Initiated by: AFS-800

AC No: 91-73
Change:

1. PURPOSE. This advisory circular (AC) provides guidelines for the development and implementation of standard pilot procedures for conducting safe aircraft operations on the airport surface. It is intended for use by Title 14 of the Code of Federal Regulations (14 CFR) part 91 operators and part 135 operators conducting single pilot flight operations. These guidelines should become an integral part of all standard operating procedures, flight operations manuals, and formal training programs. Standard use of developed procedures should be emphasized during the certification and proficiency training of all pilots. The use of standard procedures for operating on the airport surface should further be emphasized during the flight review (refer to 14 CFR part 61, section 61.56) of all certificated pilots.

NOTE: Pilots operating aircraft under 14 CFR parts 121, 125, or 135 (those part 135 flight operations where 2 or more pilots are in the cockpit) refer to AC 120-XX, Part 121, 125, and 135 Flightcrew Procedures During Taxi Operations.

2. FOCUS. This guidance focuses on the activities occurring on the flight deck/cockpit (e.g., planning, communicating, coordinating), as opposed to the actual control of the aircraft (e.g., climbing, descending, maneuvering). Although there are many similarities, taxi operations for single piloted aircraft, as opposed to taxi operations for aircraft that require more than one pilot, present distinct challenges and requirements. These distinct challenges are elaborated, when necessary, throughout the guidance. An additional section is provided concerning operations at airports without operating control towers. Finally, a section is devoted to the use of exterior aircraft lights in making an aircraft more conspicuous to all other persons directly involved in airport flight and ground operations.

3. RELATED READING MATERIAL. The following documents and web sites contain useful information regarding runway safety. FAA ACs can be found on

- Be aware
- Listen!
- Ask questions
- Stick to business
- **STOP** if in doubt
- Read back
- Once again ...

IF YOU DO NOT
UNDERSTAND
ASK!

10 Ways To Help Prevent Runway Incursions

1 See The "Big Picture"
 Monitor both ground and tower communications when possible.

2 Transmit Clearly
 Make your instructions and read backs complete and easy to understand.

3 Listen Carefully
 Listen to your clearance. Listen to what you read back. Do not let communications become automatic.

4 Copy Clearances
 Clearances can change. Keep a note pad and copy your clearance. If needed refer to your notes.

5 Situational Awareness
 Know your location. If unfamiliar with an airport keep a current airport diagram available for easy reference.

6 Admit When Lost
 If you get lost on an airport ask ATC for help. Better to damage your pride than your airplane.

7 Sterile Cockpit
 Maintain a sterile cockpit until reaching cruising altitude. Explain to your passengers that talking should be kept to a minimum.

8 Understand Signs, Lights And Markings
 Keep current with airport signs, lights and markings. Know what they mean and what action to take.

9 Never Assume
 Do not take clearances for granted. Look both ways before entering or crossing taxiways and runways.

10 Follow Procedures
 Establish safe procedures for airport operations. Then follow them.



ANM Points of Contact

(ANM Runway Safety Team)

- *Runway Safety Program Manager, ANM-1R, Jim Greene, (425) 227-1369 Jim.k.greene@faa.gov*
- *Airports Division, ANM-600, Mark Taylor, (425) 227-2625 Mark.taylor@faa.gov*
- *Flight Standards, ANM-200, Mary Hoy, (425) 227-2262 Mary.Hoy@faa.gov*
- *Airway Facilities Operations, ANM-400, Willie Eigner, (425) 227-2336 Willie.eigner@faa.gov*
- *Air Traffic Control, ANM-500, Don Bringmann, (425) 227-2550 Donald.bringmann@faa.gov*

We Listen....

We Respond



Pickup Truck versus B-747





Local Problems
require local
Solutions



AIRCRAFT MOVEMENT AREA



**DO NOT PROCEED
WITHOUT CLEARANCE
FROM PAINE TOWER**

**VEHICLES REQUIRE A
FLASHING AMBER BEACON**



**AIRCRAFT TAXIWAY
TOWER CLEARANCE REQUIRED**








GATE
E-3

**YOU ARE ENTERING AN AIR OPERATIONS AREA
AUTHORIZED VEHICLES & PERSONNEL ONLY**

VIOLATORS MAY BE PROSECUTED UNDER SNOHOMISH COUNTY CODE 15.08.651

STOP ON YELLOW LINE UNTIL GATE IS FULLY CLOSED BEHIND YOU

UNESCORTED FOLLOW-THROUGH VEHICLES ARE PROHIBITED
PLEASE REPORT VIOLATORS TO AIRPORT SECURITY 353-1606

DO NOT CROSS  WITHOUT ATC AUTHORIZATION

YIELD TO ALL AIRCRAFT
SPEED LIMIT 15



1000' Runway Visual Range





Hold Short






Cleared onto the runway





Spokane International

**Runway Incursions & Surface Incidents
1999-2001**



ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

Runway


Incursion

Surface
Incident

Pilot Error

Operational
Error

V/PD



JANUARY 1995
ANNUAL RATE OF CHANGE
0.1°W

TERMINAL/ADMINISTRATION
BUILDING

TERMINAL RAMP



ARFF

TWR
2457

RWY 3-21
S200, T200, ST175, TT400

RWY 7-25
S150, TT180, ST175, TT280

9000 X 150

WIND
SOCK

8199 X 150

AIRPORT
MAINTENANCE

TANKS

AIR
CARGO

AIR CARGO
RAMP

ILS
HOLD

ELEV
2313

1000 X 180

ILS
HOLD

HANGAR

U.S.
CUSTOMS

HANGARS

TRANSIENT
RAMP

HANGARS

HANGAR

ASOS

A 2501

HANGARS

072.2°

ILS

252.2°

47°37'N

**CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF **ALL** RUNWAY HOLDING INSTRUCTIONS
IS **REQUIRED****






117°33'W

117°32'W

117°31'W

11/04/99: A/C instructed to taxi in position and hold on Runway 21. Aircraft started take-off roll.


ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

- Runway Incursion 
- Surface Incident 
- Pilot Error 
- Operational Error 
- V/PD 

JANUARY 1995
ANNUAL RATE OF CHANGE
0.1°W

TERMINAL/ADMINISTRATION BUILDING

TERMINAL RAMP



TWR
2457

RWY 3-21
S200, T200, ST175, TT400

RWY 7-25
S150, TT180, ST175, TT280

9000 X 150

WIND
SOCK

8199 X 150

HANGAR

ASOS

A 2501

HANGARS

FIELD
ELEV
2372

ILS
HOLD

ELEV
2368

ILS
HOLD

ANG
RAMP

ANG
HANGAR

HOT CARGO

666 X 144

ELEV
2367

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS
REQUIRED

LS OLD
ELEV 2313
1000 X 180
ILS HOLD
HANGAR



U.S. CUSTOMS

HANGARS

TRANSIENT
RAMP

HANGARS

HANGAR






47°37'N

47°38'N

117°33'W

11/04/99: A/C instructed to taxi in position and hold on Runway 21. Aircraft started take-off roll.

ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

- Runway Incursion 
- Surface Incident 
- Pilot Error 
- Operational Error 
- V/PD 

JANUARY 1995
ANNUAL RATE OF CHANGE
0.1°W

TERMINAL/ADMINISTRATION
BUILDING

TERMINAL RAMP

ARFF

TWR
2457

RWY 3-21
S200, T200, ST175, TT400

RWY 7-25
S150, TT180, ST175, TT280

9000 X 150

WIND
SOCK

8199 X 150

HANGAR

ASOS

H

A 2501

HANGARS

G

X X X X X

252.2

666 X 144

ELEV
2367

HOT CARGO

ANG
RAMP

ANG
HANGAR

ILS
HOLD

ILS
HOLD

ELEV
2368

0.5% DOWN

072.2°


970 X 150


117°33'W


FIELD
ELEV
2372


CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS
REQUIRED




Runway Incursion 

Surface Incident 

Pilot Error 

Operational Error 

V/PD 

$\sqrt{A} = 18.3^\circ$

**TERMINAL/ADMINISTRATION
BUILDING**



WINE
SOCK

● **A:**



600 X 144


**CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS
REQUIRED**

ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

Runway
Incursion



Surface
Incident



Pilot Error



Operational
Error



V/PD



JANUARY 1995
ANNUAL RATE OF CHANGE
0.1°W

TERMINAL/ADMINISTRATION
BUILDING

ARFF

TERMINAL RAMP

TWR
2457

RWY 3-21
S200, T200, ST175, TT400

RWY 7-25
S150, TT180, ST175, TT280

9000 X 150

WIND
SOCK

8199 X 150

AIRPORT
MAINTENANCE

TANKS

AIR
CARGO

AIR CARGO
RAMP

ILS
HOLD

ELEV
2313

1000 X 180

ILS
HOLD

HANGAR

U.S.
CUSTOMS



TRANSIEN
RAMP

HANGARS

HANGAR

ASOS

A 2501

HANGARS

252.2

666 X 144

ELEV
2367

HOT CARGO

ANG
RAMP

ANG
HANGAR

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS
REQUIRED

4/16/2000 - A
Piper-28
taxied across
Runway 3 and
Taxiway "F"
after being
cleared to
Runway 3.

117°33'W


1

ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

Runway
Incursion



Surface
Incident



Pilot Error



Operational
Error



V/PD



JANUARY 1995
ANNUAL RATE OF CHANGE
0.1°W

TERMINAL/ADMINISTRATION
BUILDING

ARFF

TERMINAL RAMP

TWR
2457

RWY 3-21
S200, T200, ST175, TT400

RWY 7-25
S150, TT180, ST175, TT280

9000 X 150

WIND
SOCK

8199 X 150

AIRPORT
MAINTENANCE

AIR
CARGO

AIR CARGO
RAMP



EAST RAMP

HANGAR

ASOS

A 2501

HANGARS

252.2

666 X 144

HOT CARGO

ANG
RAMP

ANG
HANGAR

ILS
HOLD

ELEV
2313

1000 X 180

ILS
HOLD

HANGAR

HANGAR

TRANSIEN
RAMP

HANGARS

117°33'W

47°37'N

4/16/2000 - A
Piper-28
taxied across
Runway 3 and
Taxiway "F"
after being
cleared to
Runway 3.


CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS
REQUIRED

ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

Runway
Incursion



Surface
Incident



Pilot Error



Operational
Error



V/PD



JANUARY 1995
ANNUAL RATE OF CHANGE
0.1°W

TERMINAL/ADMINISTRATION
BUILDING

ARFF

TERMINAL RAMP

TWR
2457

RWY 3-21
S200, T200, ST175, TT400

RWY 7-25
S150, TT180, ST175, TT280

9000 X 150

WIND
SOCK

8199 X 150

AIRPORT
MAINTENANCE

TANKS

AIR
CARGO

AIR CARGO
RAMP

ILS
HOLD

ELEV
2313

ILS
HOLD

HANGAR

U.S.
CUSTOMS

HANGAR

TRANSIEN
RAMP

HANGARS

HANGAR

ASOS

A 2501

HANGARS

X X X X X

252.2

666 X 144

ELEV
2367

FIELD
ELEV
2372

072.2°

ILS
HOLD

ELEV
2368

072.2°

0.5% DOWN

ILS
HOLD

ANG
RAMP

ANG
HANGAR

HOT CARGO

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS
REQUIRED

4/16/2000 - A
Piper-28
taxied across
Runway 3 and
Taxiway "F"
after being
cleared to
Runway 3.




ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

Runway
Incursion



Surface
Incident



Pilot Error



Operational
Error



V/PD



JANUARY 1995
ANNUAL RATE OF CHANGE
0.1°W

TERMINAL/ADMINISTRATION
BUILDING

AIRPORT
MAINTENANCE

TANKS

AIR
CARGO

AIR CARGO
RAMP

ILS
HOLD

ELEV
2313

ILS
HOLD

HANGAR

U.S.
CUSTOMS

HANGAR

TRANSIEN
RAMP

HANGARS

HANGAR

ASOS

A 2501

HANGARS

RWY 3-21
S200, T200, ST175, TT400

RWY 7-25
S150, TT180, ST175, TT280

TWR
2457

9000 X 150

WIND
SOCK

8199 X 150

072.2°

ILS
HOLD

FIELD
ELEV
2372

ELEV
2368

ILS
HOLD

ANG
RAMP

ANG
HANGAR

HOT CARGO

666 X 144

ELEV
2367

47°37'N

4/16/2000 - A
Piper-28
taxied across
Runway 3 and
Taxiway "F"
after being
cleared to
Runway 3.

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS
REQUIRED

117°33'W


1

ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

Runway
Incursion



Surface
Incident



Pilot Error



Operational
Error



V/PD



JANUARY 1995
ANNUAL RATE OF CHANGE
0.1°W

TERMINAL/ADMINISTRATION
BUILDING

AIRPORT
MAINTENANCE

TANKS

AIR
CARGO

AIR CARGO
RAMP

ILS
HOLD

ELEV
2313

ILS
HOLD

HANGAR

U.S.
CUSTOMS

HANGAR

TRANSIEN
RAMP

HANGARS



TERMINAL RAMP

TWR
2457

RWY 3-21
S200, T200, ST175, TT400

RWY 7-25
S150, TT180, ST175, TT280

9000 X 150

HANGAR

ASOS

A 2501

HANGARS

8199 X 150

ANG
RAMP

ANG
HANGAR

HOT CARGO

666 X 144

ELEV
2367

072.2°

ILS
HOLD

FIELD
ELEV
2372

ELEV
2368

ILS
HOLD

117°33'W






47°37'N

4/16/2000 - A
Piper-28
taxied across
Runway 3 and
Taxiway "F"
after being
cleared to
Runway 3.

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS
REQUIRED

A Cessna 182 landing Runway 25 was instructed to exit Taxiway "D" and contact Ground Control. The C-182 then taxied across Runway 21 after contacting GC and being instructed to taxi to the ramp. A Boeing 735 had been cleared for takeoff but had not entered onto Runway 21. 10-03-2000

ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

- Runway Incursion 
- Surface Incident 
- Pilot Error 
- Operational Error 
- V/PD 

JANUARY 1995
ANNUAL RATE OF CHANGE
0.1°W

RWY 3-21
S200, T200, ST175, TT400
RWY 7-25
S150, TT180, ST175, TT280

FIELD
ELEV
2372

117°33'W

TERMINAL/ADMINISTRATION
BUILDING

TERMINAL RAMP

ARFF

TWR
2457

WIND
SOCK

8199 X 150

ANG
RAMP

ANG
HANGAR

AIR CARGO
RAMP

HANGAR

ASOS

H

HOT CARGO

666 X 144

ELEV
2367

A 2501

HANGARS

HANGARS

TRANSIENT
RAMP

HANGARS

U.S. CUSTOMS

HANGAR

ELEV
2313

ILS HOLD

1000 X 180






47°38'N

47°37'N

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS
REQUIRED

A Cessna 182 landing Runway 25 was instructed to exit Taxiway "D" and contact Ground Control. The C-182 then taxied across Runway 21 after contacting GC and being instructed to taxi to the ramp. A Boeing 735 had been cleared for takeoff but had not entered onto Runway 21. 10-03-2000

ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

- Runway Incursion 
- Surface Incident 
- Pilot Error 
- Operational Error 
- V/PD 

JANUARY 1995
ANNUAL RATE OF CHANGE
0.1°W

RWY 3-21
S200, T200, ST175, TT400
RWY 7-25
S150, TT180, ST175, TT280

FIELD
ELEV
2372

117°33'W

TERMINAL/ADMINISTRATION
BUILDING

TERMINAL RAMP

ARFF

TWR
2457

WIND
SOCK

8199 X 150

ANG
RAMP

ANG
HANGAR

HANGAR

ASOS

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H

D

G

X

X

X

X

X

X

X

X

X

X

H






D

G

X

A Cessna 182 landing Runway 25 was instructed to exit Taxiway "D" and contact Ground Control. The C-182 then taxied across Runway 21 after contacting GC and being instructed to taxi to the ramp. A Boeing 735 had been cleared for takeoff but had not entered onto Runway 21. 10-03-2000

ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

- Runway Incursion 
- Surface Incident 
- Pilot Error 
- Operational Error 
- V/PD 

JANUARY 1995
ANNUAL RATE OF CHANGE
0.1°W

TERMINAL RAMP

TERMINAL/ADMINISTRATION
BUILDING

ARFF

TWR
2457

RWY 3-21
S200, T200, ST175, TT400

RWY 7-25
S150, TT180, ST175, TT280

9000 X 150

WIND
SOCK

8199 X 150

072.2°

ILS
HOLD

FIELD
ELEV
2372

ELEV
2368

ILS
HOLD

ANG
RAMP

ANG
HANGAR

HANGAR

ASOS

EAST RAMP

HANGARS

HANGARS

TRANSIENT
RAMP

HANGARS

HANGARS

A 2501

252.2°

666 X 144

ELEV
2367

HOT CARGO

AIR CARGO
RAMP

ELEV
2313

ILS
HOLD

HANGAR

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS
REQUIRED

117°33'W






1


47°37'N

47°38'N

Beech BE58, was instructed to taxi to Runway 7 and crossed the hold line without authorization. Local controller observed the incursion and the conflict with B-737, on approximately ½ mile final same runway. B-737 was sent around. 6-20-2001






ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

- Runway Incursion 
- Surface Incident 
- Pilot Error 
- Operational Error 
- V/PD 



CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS
REQUIRED

ATIS 124.325 254.375
SPOKANE TOWER
118.3 257.8
GND CON
121.9 348.6
CLNC DEL
127.55

- Runway Incursion 
- Surface Incident 
- Pilot Error 
- Operational Error 
- V/PD 

JANUARY 1995
ANNUAL RATE OF CHANGE
0.1°W

TERMINAL/ADMINISTRATION
BUILDING

TERMINAL RAMP



TWR
2457

RWY 3-21
S200, T200, ST175, TT400
RWY 7-25
S150, TT180, ST175, TT280

9000 X 150

WIND
SOCK

8199 X 150

AIRPORT
MAINTENANCE

TANKS

AIR
CARGO

AIR CARGO
RAMP

ILS
HOLD

ELEV
2313

ILS
HOLD

HANGAR

U.S. CUSTOMS

HANGARS

TRANSIENT
RAMP

EAST
RAMP

HANGAR

ASOS

HANGARS

252.2°

666 X 144

ELEV
2367

FIELD
ELEV
2372

ILS
HOLD

072.2°

DOWN

ANG
RAMP

If in doubt,
ASK!

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.





Local Problems require local Solutions

- Airport Traffic Control Tower
- Spokane International Airport